



CARDIAC TROPONIN PANEL # MDXPCT- 016
0.5 ml Matched Serum, K2 EDTA Plasma, and Li Heparin Plasma

ID #	Age	Gender	Ethnicity	Race	Smoker/Non-Smoker	Cause of elevated Troponin	Symptoms	Date of Event	Admitted AM/PM
7026	48	Male	Hispanic	Caucasian	Smoker	Heart Attack	Chest pain, left arm pain	5/2/2019	PM

Sample ID	Draw	Time Point	BP	Draw Date	Troponin	Myoglobin	Matrix
A11703387	1	12-18 HRS	160/92	5/3/2019	34.0 ng/mL	4.8 ng/mL	SERUM
A11703388	1	12-18 HRS	160/92	5/3/2019	Not Tested	Not Tested	K2 EDTA
A11703389	1	12-18 HRS	160/92	5/3/2019	Not Tested	Not Tested	LIH
A11703393	2	24 HRS POST	160/90	5/4/2019	28.2 ng/mL	2.5 ng/mL	SERUM
A11703394	2	24 HRS POST	160/90	5/4/2019	Not Tested	Not Tested	K2 EDTA
A11703395	2	24 HRS POST	160/90	5/4/2019	Not Tested	Not Tested	LIH
A11703399	3	48 HRS POST	150/86	5/5/2019	24.2 ng/mL	3.1 ng/mL	SERUM
A11703400	3	48 HRS POST	150/86	5/5/2019	Not Tested	Not Tested	K2 EDTA
A11703401	3	48 HRS POST	150/86	5/5/2019	Not Tested	Not Tested	LIH
A11703405	4	72 HRS POST	140/90	5/6/2019	18.0 ng/mL	1.8 ng/mL	SERUM
A11703406	4	72 HRS POST	140/90	5/6/2019	Not Tested	Not Tested	K2 EDTA
A11703407	4	72 HRS POST	140/90	5/6/2019	Not Tested	Not Tested	LIH

Troponin Testing was performed on Tosoh AIA-360/Myoglobin Testing was performed on RayBio Human Myoglobin ELISA Kit

CAUTION: HUMAN BLOOD

All materials listed above are considered to be potentially infectious and should be handled with universal precautions.